ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0289, W0299, W0301, I0305, I0232, I0847, W0845, W	Chikkanna Lyt, Maheshwari Nagar Main Rd, Bimel Behind Rd, Church Rd, NA, Maheshwari Nagar 4th Main R	Vemanna layout main road
Segment No.	**Total Length (m)**	
10/C-W0289/S092744	472.03	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	63.61	77.561273	13.061366	77.561153	13.060803	Vemanna layout	cross road
2	61.60	77.560924	13.061421	77.560814	13.060874	Vemanna layout	cross road
3	67.92	77.561182	13.061430	77.561321	13.062029	Gas gowdan road	cross road
4	65.86	77.560921	13.061468	77.561070	13.062045	Vemanna layout	cross road
5	213.04	77.560070	13.061589	77.561570	13.061922	Chamundeswari layout	Vemanna layout main road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to balance roads and drains in ward no. 10 Vidyaranyapura sub division.	3500000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Asphalting and Rcc drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		010-16-000001
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/63/2017-18	06/05/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/06/2017	30/06/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Venkategowda		0.00
Phone No.	**E-Mail ID**	
9845507797		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		basavaraj k.b
Date of Inspection	**Remarks**	
01/07/2017		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0289, W0299, W0301, I0305,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Parameshwaraiah	01/07/2017	31/07/2017	Approved
SE	K.M.Vasu	01/07/2017	31/07/2017	Verified
EE	H.T.Mohandas	01/07/2017	31/07/2017	Verified
AEE	shivakumar m gowdar	01/07/2017	31/07/2017	Verified
AE	Basavaraj K.B	01/07/2017	31/07/2017	Mobile verification done
AE	Basavaraj K.B	01/07/2017	31/07/2017	Forwarded

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0289, W0299, W0301, I0305,